CyberPower®

Quick Start Guide for USB 2.0 4 Port Hub



Model No. CP-H420P

This USB Hub makes the most of your computer and workspace by increasing the number of available USB ports. There has never been a more convenient way to expand your USB capacity

Table of Contents

Introduction	1
System Requirements	2
Package Contents	2
Specifications	3
Product Overview	4
Installation	5
Appendix A (Troubleshooting)	8
Appendix B (Radio Interference Statement)	9
Appendix C (Product Limited Liabilities Warranty)	10

Thank you for purchasing a CyberPower product. To enjoy all the features and benefits of this USB Hub, please read and follow all installation and operation instruction completely.

Introduction

USB(Universal Serial Bus) is currently the standard for most computers, notebooks and peripherals. The USB connections allow the user to easily connect multiple devices. The CyberPower USB 2.0 4 Port Hub (Model. CP-H420P) provides additional ports to connect up to 4 USB devices to a single USB port on your computer.

The Quick Start Guide contains easy instructions in order to show you how to set up and start using your CyberPower USB Hub

System Requirements

Any PC or Macintosh computer with an available USB port and USB-compliant operating system(Windows 98/98SE/2000/ME/XP, MacOS 8.6 or above, etc.)

Package Contents

This package includes:

- USB 2.0 4 Port Hub (Model CP-H420P)
- AC Power Adapter
- 1.5m A-miniB USB cable
- User Manual

Specifications

FUNCTION		SPECIFICATION
USB Ports	Downstream	1
	Upstream	4
LEDs	Power	1(Blue)
	Battery Discharge	1(Green)
Power Mode		Self-Powered
Output Voltage(per port)		+5V DC
Output Currect(per port)		500mA(max)
Operating Temperature		5°C~40°C
Storage Temperature		-20°C~60°C
Humidity		0~80%RH. Noncondensing
Housing		Plastic
Weight		46g
Dimensions		67.0 x 64.0 x 20.0 mm

Product Overview



Model CP-H420P

Product Overview - continued

1)**Power Indicator** – Blue LED will light when USB Hub is receiving power.

2)**Downstream Ports** – Connect your USB devices to these 4 ports.

3)**Port Status Indicators** – Green LEDs indicate port status and over corrent detection. When a device is connected to one of the ports, the associated LED will light. If an over current condition occurs, the LED for that port will turn off, indicating a problem with that device.

4)**Root(Upstream) Ports** – Connect your computer to this port to provide a link between the hub and devices.

5)**AC Adapter Power Connection** – Connect your ac power adapter here. This hub operates in self-powered mode to ensure sufficient power is provided to connect USB devices.

Installation

This USB Hub is a plug-and-play device. Your computer will display the **ADD NEW Hardware** Wizard after connecting the hub to your computer. Installation may be done whether your computer is powered on or off. It is not necessary to restart your computer after installation.

1)Connect the A-miniB USB cable(include in this package) to the Upstream port on the USB Hub, then connect the other end of the cable to an unused USB port on your computer.

2)Connect your USB devices to the Downstream ports on the USB Hub.

Installation - continued

Self-Power the Hub:

Plug the DC power adapter into the jack,then plug the power adapter into a well outlet if additional power is required for connected USB devices.

NOTE:

To maximize USB Hub's performance, **it is recommended to plug CyberPower AC power adapter while using**